From:

Deltoral, Miguel

Sent:

Friday, September 22, 2017 4:14 AM

To:

Sulei, Erik

Subject:

FOIA-EPA-R5-2017-011686 (email received)

Attachments:

image1.JPG

Miguel A. Del Toral Regulations Manager U.S. EPA R5 GWDWB 77 West Jackson Blvd, (WG-15J)

Chicago, IL 60604

Phone: (312) 886-5253

From: Marc Edwards <edwardsm@vt.edu> Sent: Thursday, August 3, 2017 08:04 PM

To: Deltoral, Miguel

Subject: This sounds like the story you just told me. Elevated blood lead and 3000+ ppb lead in water.

I will check if she ran the story.

From: Pierret, Ann C. [mailto:ann.pierret@abc12.com]

Sent: Thursday, July 27, 2017 12:16 PM

To: edwardsm@vt.edu

Subject: Fwd: Media Inquiry (ABC12)

Forgot to attach the photo.



Ann Pierret Reporter ABC12 News (810) 240 - 8741

Begin forwarded message:

From: "Pierret, Ann C." <ann.pierret@abc12.com>

Date: July 27, 2017 at 12:13:14 PM EDT

To: "edwardsm@vt.edu" <edwardsm@vt.edu>

Subject: Media Inquiry (ABC12)

Hi Dr. Edwards,

I am working on a story today with a woman who reached out to us that lives in the Flint College Cultural neighborhood.

She tells me she's been part of the sentinel testing since February. She also brings her test kits to the water resource sites every few weeks.

Her sentinel test results from July 5<sup>th</sup> show her "Lead Calculated to 1L" at 3818ppb (photo attached). Then, she got results on the 12<sup>th</sup> that showed it 320ppb higher.

She tells me she spoke with someone from DEQ about the results last week and they told her not to worry about the high number, that's a snap shot in time, it's not surprising that it spiked.

On top of that, she has used the water foundry, dishes and showering and a finger prick test just came back showing her blood tested with lead.

She doesn't have lead pipes, she says she has a copper line and copper plumbing. She replaced her hot water heater in September and her faucet fixtures in January. There is a galvanized pipe where the copper line meets the meter. She also says they have not been doing work in her neighborhood recently to replace anybody else's pipes.

So, my question to you is – what could possibly be going on? What does she need to be doing to protect herself?

If it helps, her address is \_\_\_\_\_\_ t MI 48503

I'm hoping to run something tonight in our 5 or 6pm newscasts. Let me know!

Thank you, Ann Pierret Reporter, ABC12 News 810-240-8741

Lansing, MI 48909 TEL: (517) 335-8184

> Sample Number LH25195

Report To:
FLINT, MI
48503

Official Laboratory Report

System Name/Owner: Collection Address:

Collected By:

County: Sample Point:

inth

FLINT 48503
Genesee
KITCHEN

Date Collected: 07/05/2017 Date Received: 07/10/2017

Metal Result In Parts Per Billion (ppb)

Copper 250 mL Sample 480

Copper 750 mL Sample 280

Copper Calculated to 1L 330

Lead 250 mL Sample 5533

Lead 750 mL Sample

Lead Calculated to 1L